

Pavement Management Recommendations

Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data Collected August - September 2003







Map Compiled March 2004 by Statewide Pavement Management, Design and Engineering Services, State of Alaska DOT&PF

Southeast Region Overview

Rut Depth Measurements Based on Pavement Profiler Data Collected August - September 2003


Pavement Management Recommendations





RUT DEPTH Recommendations Do nothing 0.24 - 0.49 Localized Patching 0.49 - 0.74 Design rehabilitation project and patch as needed Construct rehabilitation project or immediate maintenance


Map Compiled December 2003 by Statewide Pavement Management, Design and Engineering Services, State of Alaska DOT&PF






















Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data








Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data Collected August - September 2003








Map Compiled March 2004 by Statewide Pavement Management, Design and Engineering Services, State of Alaska DOT&PF


Rut Depth Measurements Based on Pavement Profiler Data Collected August - September 2003


Pavement Management Recommendations






Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data Collected August - September 2003







Rut Depth Measurements Based on Pavement Profiler Data Collected August - September 2003

Pavement Management Recommendations









Rut Depth Measurements Based on Pavement Profiler Data Collected August - September 2003


Pavement Management Recommendations








Pavement Management Recommendations

Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data Collected August - September 2003













Rut Depth Measurements Based on Pavement Profiler Data Collected August - September 2003

Pavement Management Recommendations













Wearing Course Life Estimates Wearing Course Life 0 Years 1 - 2 Years Thorne Bay Rd 3 - 4 Years 5 - 6 Years 7 - 10 Years 11 + Years Map Compiled March 2004 by Statewide Pavement Management, Design and Engineering Services, State of Alaska DOT&PF llis Ferry Terminal 10 15 20 Miles











Present Serviceability Rating - PSR Including IRI and Rutting Based on Pavement Profiler Data Collected August - September 2003

